


MEG Connections



- Connect RF to RF Input-1 (SES-18 H)
- Connect Ethernet to Interface-3 for management
- Connect the type of output you ordered to a device which will validate signal
 - For ASI – Connect to ASI/SDI BNC
 - For SDI – Connect to ASI/SDI BNC
 - For TSoip – Connect to Multicast interface